

Forum:[Hack Forums](#)

Thread: [Computer doesn't wake up from sleep mode instantly, takes few minutes](#)

vtecm - May 7, 2014, 3:26 am

I've been having problems with my computer for under a year now, where when I try to wake my computer from sleep mode it won't load up instantly, it'll wake after a few minutes.

I got a new hard drive and put my OS on that and still hasn't solved the problem.

Specs:

Windows 8 genuine
i7 3770k
ASRock Extreme 4 Z77
8gb Kingston 2x4GB 1333MHZ

zeroday - May 7, 2014, 3:47 am

It just might be because your computer has been asleep for sometime it just takes a couple of minutes to warm up.

Aura - May 7, 2014, 5:18 am

Did you configure your Windows to go in sleep mode or hibernation mode ? It should be located in your Power Settings accesible via the Control Panel.

vtecm - May 7, 2014, 4:16 pm

These are my power options for sleep.

It generally only happens after a long sleep otherwise it'll usually boot up instantly.

Aura - May 7, 2014, 4:23 pm

(May 7, 2014 04:16 PM)vtecm Wrote: [\[CITE\]](#) These are my power options for sleep.

It generally only happens after a long sleep otherwise it'll usually boot up instantly.
Turn off the Hybrid Sleep setting, that's the issue.

vtecm - May 7, 2014, 4:27 pm

Thanks for the help, I think it'll work. Will have to wait and see :).

Aura - May 7, 2014, 4:31 pm

(May 7, 2014 04:27 PM)vtecm Wrote: [\[CITE\]](#) Thanks for the help, I think it'll work. Will have to wait and see :).

That's good, keep us updated on the results !

vtecm - May 9, 2014, 4:44 pm

Unfortunately it didn't fix the problem :(

Aura - May 9, 2014, 5:15 pm

(May 9, 2014 04:44 PM)vtectm Wrote: [\[CITE\]](#) Unfortunately it didn't fix the problem :(
You know what ? I would run a chkdsk on your HDD just to see if it doesn't have any bad sectors that affects his performance and state when waking up from a sleep mode.

Code chkdsk /r

Tesseract - May 9, 2014, 9:07 pm

(May 9, 2014 04:44 PM)vtectm Wrote: [\[CITE\]](#) Unfortunately it didn't fix the problem :(
Try that after doing or so

To fix the hibernation issue I suggest that you open elevated command prompt window with this command:

Code Sfc /scannow
And then press enter.

If you like I can teamview you here and I can fix the problem. PM me credentials if you're interested.

vtectm - June 5, 2014, 3:52 am

I got no errors. Not sure why it's doing this. I've changed the HDD, graphics card and still happening.

MoonSun - June 5, 2014, 4:00 am

Did you reinstall the operating system? You should try.

vtectm - June 5, 2014, 4:26 am

I tried already. I went from W7 to W8 then 8.1 still happens.

Aura - June 5, 2014, 4:48 am

(Jun 5, 2014 03:52 AM)vtectm Wrote: [\[CITE\]](#) I got no errors. Not sure why it's doing this. I've changed the HDD, graphics card and still happening.
Did you run both the chkdsk and the sfc scan ?

Tesseract - June 5, 2014, 8:14 am

(Jun 5, 2014 04:26 AM)vtectm Wrote: [\[CITE\]](#) I tried already. I went from W7 to W8 then 8.1 still happens.

You must run a system file check and a check disk. Before the check disk, however, I'd like you to try and perform this:

Open an elevated command prompt window then type:
Code dism /online /Cleanup-Image /RestoreHealth
and then hit enter.

See if it fixes the issue.

Keep me el posted.

oddix - June 5, 2014, 10:36 am

is this a laptop or custom built computer ? might have something with the hard disk win is located on. i had this problem before. to fix it i bought a cheap ssd, then booted win7 on the new hardisk. (it will also make the computer faster i guess :P)

Freebooter - June 5, 2014, 10:38 am

Updated the graphic card driver it may be causing the problem.

vtecm - June 21, 2014, 6:48 am

Just wanted to update the post, the problem is still happening. Tried what you said MaiTriCKs. Also, this only happens when waking from sleep. If the computer is completely shutdown it boots fine.

@Freebooter. Graphic driver isn't the problem. Have tried latest version when I was running integrated Intel 4000, tried my friend's GTX670 on latest driver & then I finally bought my 280x and still happens.

vtecm - June 22, 2014, 7:21 am

Anyone got any ideas? Not sure why this happens, taking minutes to recover from sleep mode.

Tesseract - June 22, 2014, 11:48 am

Could you try cleaning up system files by going to Start Menu > Disk Cleanup > Right click run as Admin > Clean up files... > Clean up system files button > Check everything, clean up.

See if that solves the issue.

Aura - June 22, 2014, 1:54 pm

While we're on that whole troubleshooting procedure, you should also consider upgrading from Windows 8 to Windows 8.1. There's good chances that it might solve your issue.

<http://windows.microsoft.com/en-us/windows-8/update-from-windows-8-tutorial>

Tranquility - June 22, 2014, 2:34 pm

vtecm, when you resume your computer from sleep, does any logos appear just as it would during booting?

As other people already were thinking along the hibernation direction, I'm surprised to see that none of them suggested to disable that option.

Open an elevated command prompt and type the following:

Code `powercfg.exe /hibernate off`

Afterwards reboot your computer and do the following in an elevated command prompt:

Code `powercfg -energy -output %USERPROFILE%\Desktop\Energy_Report.html`

I have another option which is to disable & re-enable the hibernate file to create a more updated hiberfil.sys file, but as you're using sleep this shouldn't apply to this situation. For this reason I'm leaving that out for now. Post back here with the results (or a link to the HTML output file).

Aura - June 22, 2014, 2:36 pm

(Jun 22, 2014 02:34 PM)Tranquility Wrote: [\[CITE\]](#) vtecm, when you resume your computer from sleep, does any logos appear just as it would during booting?

As other people already were thinking along the hibernation direction, I'm surprised to see that none of them suggested to disable that option.

Open an elevated command prompt and type the following:

Code `powercfg.exe /hibernate off`

Afterwards reboot your computer and do the following in an elevated command prompt:

Code `powercfg -energy -output %USERPROFILE%\Desktop\Energy_Report.html`

I have another option which is to disable & re-enable the hibernate file to create a more updated hiberfil.sys file, but as you're using sleep this shouldn't apply to this situation. For this reason I'm leaving that out for now. Post back here with the results (or a link to the HTML output file).

I used that command on Grin's laptop to fix another issue, but also to make via the registry a power plan by default and remove the others. It failed but let's see if it works on OP's computer.

Tranquility - June 22, 2014, 2:39 pm

(Jun 22, 2014 02:36 PM)Aur? Wrote: [\[CITE\]](#) I used that command on Grin's laptop to fix another issue, but also to make via the registry a power plan by default and remove the others. It failed but let's see if it works on OP's computer.

Else I was thinking of something along the lines of this in an elevated prompt:

```
Code cd \  
powercfg /h off  
powercfg /h on  
dir /ahs
```

And verify if the hiberfil.sys will have today's date and a time of the last few minutes assigned to it. It sort of seems his sleep mode goes to hibernation no matter what, according to his description.

Tesseract - June 22, 2014, 2:41 pm

(Jun 22, 2014 02:39 PM)Tranquility Wrote: [\[CITE\]](#) And verify if the hiberfil.sys will have today's date and a time of the last few minutes assigned to it. It sort of seems his sleep mode goes to hibernation no matter what, according to his description.

That seems like an interesting theory. We'll see how it plays out for OP.

I don't think that hibernation toggling is going to work, though. But it is worth a try.

EDIT:

Your command does not work, at least in Windows 8.

Code powercf -energy will create a file he can retrieve in
"C:\Windows\System32\energy-report.html" instead.

Then OP needs to copy that file to the Desktop to gain proper access to the file to be opened in Internet Explorer or Google Chrome.

Aura - June 22, 2014, 5:33 pm

(Jun 22, 2014 02:41 PM)MaiTriCks Wrote: [\[CITE\]](#) That seems like an interesting theory. We'll see how it plays out for OP.

I don't think that hibernation toggling is going to work, though. But it is worth a try.

EDIT:

Your command does not work, at least in Windows 8.

Code powercf -energy will create a file he can retrieve in
"C:\Windows\System32\energy-report.html" instead.

Then OP needs to copy that file to the Desktop to gain proper access to the file to be opened in Internet Explorer or Google Chrome.

Either you didn't open the command prompt on the desktop, or you didn't enter the full command, you only entered half of it. The full command is :

```
Code powercfg -energy -output %USERPROFILE%\Desktop\Energy_Report.html
```

Tesseract - June 22, 2014, 7:36 pm

(Jun 22, 2014 05:33 PM)Aur? Wrote: [\[CITE\]](#) Either you didn't open the command prompt on the desktop, or you didn't enter the full command, you only entered half of it. The full command is :

```
Code powercfg -energy -output %USERPROFILE%\Desktop\Energy_Report.html
```

I am pretty sure my command prompt isn't broken ? , and it is indeed an invalid command. ?

Anyways if this does not work for you OP, use the solution I posted above. It works much better my way.

vtecm - June 23, 2014, 3:59 am

(Jun 22, 2014 01:54 PM)Aur? Wrote: [\[CITE\]](#) While we're on that whole troubleshooting procedure, you should also consider upgrading from Windows 8 to Windows 8.1. There's good chances that it might solve your issue.

<http://windows.microsoft.com/en-us/windows-8/update-from-windows-8-tutorial>

I'm already running 8.1.

(Jun 22, 2014 07:36 PM)MaiTriCks Wrote: [\[CITE\]](#)

I am pretty sure my command prompt isn't broken ? , and it is indeed an invalid command. ?

Anyways if this does not work for you OP, use the solution I posted above. It works much better my way.

The command worked. Might be glitched, had that happen to me a few times where some commands wouldn't work, but it fixed when I went to 8.1.

(Jun 22, 2014 02:34 PM)Tranquility Wrote: [\[CITE\]](#) vtecm, when you resume your computer from sleep, does any logos appear just as it would during booting?

As other people already were thinking along the hibernation direction, I'm surprised to see that none of them suggested to disable that option.

Open an elevated command prompt and type the following:

```
Code powercfg.exe /hibernate off
```

Afterwards reboot your computer and do the following in an elevated command prompt:

```
Code powercfg -energy -output %USERPROFILE%\Desktop\Energy_Report.html
```

I have another option which is to disable & re-enable the hibernate file to create a more updated hiberfil.sys file, but as you're using sleep this shouldn't apply to this situation. For this reason I'm leaving that out for now. Post back here with the results (or a link to the HTML output file).

Spoiler ([Click to View](#))

Power Efficiency Diagnostics Report

Computer Name EVO

Scan Time 2014-06-23T10:52:03Z

Scan Duration 60 seconds

System Manufacturer To Be Filled By O.E.M.

System Product Name To Be Filled By O.E.M.

BIOS Date 07/11/2013

BIOS Version P2.90

OS Build 9600

Platform Role PlatformRoleDesktop

Plugged In true

Process Count 75
Thread Count 998
Report GUID {5809d9e9-e43c-474e-9482-12b46d63931b}
Analysis Results

Errors

Power Policy:Power Plan Personality is High Performance (Plugged In)
The current power plan personality is High Performance when the system is plugged in.

Power Policy:Sleep timeout is disabled (Plugged In)
The computer is not configured to automatically sleep after a period of inactivity.

Power Policy:Minimum processor performance state is 100% (Plugged In)
The processor is not configured to automatically reduce power consumption based on activity.

Power Policy:PCI Express ASPM is disabled (Plugged In)
The current power policy for PCI Express Active State Power Management (ASPM) is configured to Off.

System Availability Requests:System Required Request
The program has made a request to prevent the system from automatically entering sleep.
Requesting Process \Device\HarddiskVolume2\Program Files\Windows Media
Player\wmpnetwk.exe

USB Suspend:USB Device not Entering Selective Suspend
This device did not enter the USB Selective Suspend state. Processor power management may be prevented when this USB device is not in the Selective Suspend state. Note that this issue will not prevent the system from sleeping.
Device Name USB Mass Storage Device
Host Controller ID PCI\VEN_1B21&DEV_1042
Host Controller Location PCI bus 8, device 0, function 0
Device ID USB\VID_0BC2&PID_3300
Port Path 3

USB Suspend:USB Device not Entering Selective Suspend
This device did not enter the USB Selective Suspend state. Processor power management may be prevented when this USB device is not in the Selective Suspend state. Note that this issue will not prevent the system from sleeping.
Device Name USB Composite Device
Host Controller ID PCI\VEN_8086&DEV_1E31
Host Controller Location PCI bus 0, device 20, function 0
Device ID USB\VID_1532&PID_0037
Port Path 1

USB Suspend:USB Device not Entering Selective Suspend
This device did not enter the USB Selective Suspend state. Processor power management may be prevented when this USB device is not in the Selective Suspend state. Note that this issue will not prevent the system from sleeping.
Device Name USB Composite Device
Host Controller ID PCI\VEN_8086&DEV_1E31
Host Controller Location PCI bus 0, device 20, function 0
Device ID USB\VID_046D&PID_C248
Port Path 2

CPU Utilisation:Processor utilisation is high
The average processor utilisation during the trace was high. The system will consume less power when the average processor utilisation is very low. Review processor utilisation for individual processes to determine which applications and services contribute the most to total processor utilisation.
Average Utilisation (%) 5.10

Platform Power Management Capabilities:PCI Express Active-State Power Management (ASPM) Disabled

PCI Express Active-State Power Management (ASPM) has been disabled due to a known incompatibility with the hardware in this computer.

Warnings

Platform Timer Resolution:Platform Timer Resolution

The default platform timer resolution is 15.6 ms (15625000 ns) and should be used whenever the system is idle. If the timer resolution is increased, processor power management technologies may not be effective. The timer resolution may be increased due to multimedia playback or graphical animations.

Current Timer Resolution (100 ns units) 10009

Maximum Timer Period (100 ns units) 156250

Platform Timer Resolution:Outstanding Timer Request

A program or service has requested a timer resolution smaller than the platform maximum timer resolution.

Requested Period 10000

Requesting Process ID 3804

Requesting Process Path \Device\HarddiskVolume1\Program Files (x86)\Origin\Origin.exe

Platform Timer Resolution:Outstanding Timer Request

A program or service has requested a timer resolution smaller than the platform maximum timer resolution.

Requested Period 10000

Requesting Process ID 3584

Requesting Process Path \Device\HarddiskVolume2\Program Files (x86)\Google\Chrome\Application\chrome.exe

Platform Timer Resolution:Outstanding Timer Request

A program or service has requested a timer resolution smaller than the platform maximum timer resolution.

Requested Period 10000

Requesting Process ID 4192

Requesting Process Path \Device\HarddiskVolume2\Program Files (x86)\Razer\Synapse\RzSynapse.exe

Platform Timer Resolution:Outstanding Timer Request

A program or service has requested a timer resolution smaller than the platform maximum timer resolution.

Requested Period 10000

Requesting Process ID 3940

Requesting Process Path \Device\HarddiskVolume2\Program Files (x86)\Google\Chrome\Application\chrome.exe

Platform Timer Resolution:Outstanding Timer Request

A program or service has requested a timer resolution smaller than the platform maximum timer resolution.

Requested Period 10000

Requesting Process ID 4148

Requesting Process Path \Device\HarddiskVolume2\Program Files (x86)\Google\Chrome\Application\chrome.exe

Power Policy:Display timeout is long (Plugged In)

The display is configured to turn off after longer than 10 minutes.

Timeout (seconds) 900

Power Policy:Dim timeout is long (Plugged In)

The display is configured to automatically dim after longer than 10 minutes.

Timeout (seconds) 885

CPU Utilisation:Individual process with significant processor utilisation.

This process is responsible for a significant portion of the total processor utilisation recorded during the trace.

Process Name Origin.exe

PID 3804

Average Utilisation (%) 1.40

Module Average Module Utilisation (%)

\SystemRoot\system32\ntoskrnl.exe 0.26

\Device\HarddiskVolume2\Windows\SysWOW64\msvcr100.dll 0.26

\Device\HarddiskVolume1\Program Files (x86)\Origin\Qt5Core.dll 0.24

CPU Utilisation:Individual process with significant processor utilisation.

This process is responsible for a significant portion of the total processor utilisation recorded during the trace.

Process Name chrome.exe

PID 3940

Average Utilisation (%) 0.84

Module Average Module Utilisation (%)

\Device\HarddiskVolume2\Program Files

(x86)\Google\Chrome\Application\35.0.1916.153\chrome_child.dll 0.70

\SystemRoot\system32\ntoskrnl.exe 0.07

\Device\HarddiskVolume2\Windows\SysWOW64\ntdll.dll 0.01

CPU Utilisation:Individual process with significant processor utilisation.

This process is responsible for a significant portion of the total processor utilisation recorded during the trace.

Process Name chrome.exe

PID 1840

Average Utilisation (%) 0.73

Module Average Module Utilisation (%)

\Device\HarddiskVolume2\Program Files

(x86)\Google\Chrome\Application\35.0.1916.153\chrome.dll 0.41

\SystemRoot\system32\ntoskrnl.exe 0.11

\SystemRoot\System32\win32k.sys 0.06

CPU Utilisation:Individual process with significant processor utilisation.

This process is responsible for a significant portion of the total processor utilisation recorded during the trace.

Process Name chrome.exe

PID 4148

Average Utilisation (%) 0.48

Module Average Module Utilisation (%)

\Device\HarddiskVolume2\Windows\SysWOW64\atumdag.dll 0.11

\Device\HarddiskVolume2\Program Files

(x86)\Google\Chrome\Application\35.0.1916.153\chrome_child.dll 0.09

\Device\HarddiskVolume2\Program Files

(x86)\Google\Chrome\Application\35.0.1916.153\libglesv2.dll 0.09

Information

Platform Timer Resolution:Timer Request Stack

The stack of modules responsible for the lowest platform timer setting in this process.

Requested Period 10000

Requesting Process ID 3804

Requesting Process Path \Device\HarddiskVolume1\Program Files (x86)\Origin\Origin.exe

Calling Module Stack \Device\HarddiskVolume2\Windows\SysWOW64\ntdll.dll

\Device\HarddiskVolume2\Windows\SysWOW64\kernel32.dll

\Device\HarddiskVolume2\Windows\SysWOW64\winmm.dll
\Device\HarddiskVolume1\Program Files (x86)\Origin\Qt5Core.dll
Platform Timer Resolution:Timer Request Stack
The stack of modules responsible for the lowest platform timer setting in this process.
Requested Period 10000
Requesting Process ID 3584
Requesting Process Path \Device\HarddiskVolume2\Program Files
(x86)\Google\Chrome\Application\chrome.exe
Calling Module Stack \Device\HarddiskVolume2\Windows\SysWOW64\ntdll.dll
\Device\HarddiskVolume2\Windows\SysWOW64\kernel32.dll
\Device\HarddiskVolume2\Program Files
(x86)\Google\Chrome\Application\35.0.1916.153\chrome_child.dll
Platform Timer Resolution:Timer Request Stack
The stack of modules responsible for the lowest platform timer setting in this process.
Requested Period 10000
Requesting Process ID 4192
Requesting Process Path \Device\HarddiskVolume2\Program Files
(x86)\Razer\Synapse\RzSynapse.exe
Calling Module Stack \Device\HarddiskVolume2\Windows\SysWOW64\ntdll.dll
\Device\HarddiskVolume2\Windows\SysWOW64\kernel32.dll
\Device\HarddiskVolume2\Windows\Microsoft.NET\Framework\v4.0.30319\WPF\wpfgfx_v0400.dll
\Device\HarddiskVolume2\Windows\SysWOW64\kernel32.dll
\Device\HarddiskVolume2\Windows\SysWOW64\ntdll.dll
Platform Timer Resolution:Timer Request Stack
The stack of modules responsible for the lowest platform timer setting in this process.
Requested Period 10000
Requesting Process ID 3940
Requesting Process Path \Device\HarddiskVolume2\Program Files
(x86)\Google\Chrome\Application\chrome.exe
Calling Module Stack \Device\HarddiskVolume2\Windows\SysWOW64\ntdll.dll
\Device\HarddiskVolume2\Windows\SysWOW64\kernel32.dll
\Device\HarddiskVolume2\Program Files
(x86)\Google\Chrome\Application\35.0.1916.153\chrome_child.dll
\Device\HarddiskVolume2\Windows\SysWOW64\kernel32.dll
\Device\HarddiskVolume2\Windows\SysWOW64\ntdll.dll
Platform Timer Resolution:Timer Request Stack
The stack of modules responsible for the lowest platform timer setting in this process.
Requested Period 10000
Requesting Process ID 4148
Requesting Process Path \Device\HarddiskVolume2\Program Files
(x86)\Google\Chrome\Application\chrome.exe
Calling Module Stack \Device\HarddiskVolume2\Windows\SysWOW64\ntdll.dll
\Device\HarddiskVolume2\Windows\SysWOW64\kernel32.dll
\Device\HarddiskVolume2\Windows\SysWOW64\d3d9.dll
\Device\HarddiskVolume2\Program Files
(x86)\Google\Chrome\Application\35.0.1916.153\libglesv2.dll
\Device\HarddiskVolume2\Program Files (x86)\Google\Chrome\Application\35.0.1916.153\libegl.dll
\Device\HarddiskVolume2\Program Files
(x86)\Google\Chrome\Application\35.0.1916.153\chrome_child.dll
Power Policy:Active Power Plan
The current power plan in use
Plan Name OEM High Performance
Plan GUID {8c5e7fda-e8bf-4a96-9a85-a6e23a8c635c}

Power Policy:Power Plan Personality (Plugged In)

The personality of the current power plan when the system is plugged in.

Personality High Performance

Power Policy:802.11 Radio Power Policy is Maximum Performance (Plugged In)

The current power policy for 802.11-compatible wireless network adapters is not configured to use low-power modes.

Power Policy:Video quality (Plugged In)

Enables Windows Media Player to optimise for quality or power savings when playing video.

Quality Mode Optimise for Video Quality

Battery:Analysis Success

Analysis was successful. No energy efficiency problems were found. No information was returned.

Platform Power Management Capabilities:Supported Sleep States

Sleep states allow the computer to enter low-power modes after a period of inactivity. The S3 sleep state is the default sleep state for Windows platforms. The S3 sleep state consumes only enough power to preserve memory contents and allow the computer to resume working quickly. Very few platforms support the S1 or S2 Sleep states.

S1 Sleep Supported false

S2 Sleep Supported false

S3 Sleep Supported true

S4 Sleep Supported true

Platform Power Management Capabilities:Connected Standby Support

Connected standby allows the computer to enter a low-power mode in which it is always on and connected. If supported, connected standby is used instead of system sleep states.

Connected Standby Supported false

Platform Power Management Capabilities:Processor Power Management Capabilities

Effective processor power management enables the computer to automatically balance performance and energy consumption.

Group 0

Index 0

Idle State Count 3

Idle State Type ACPI Idle © States

Nominal Frequency (MHz) 3501

Maximum Performance Percentage 100

Lowest Performance Percentage 45

Lowest Throttle Percentage 45

Performance Controls Type ACPI Performance (P) / Throttle (T) States

Platform Power Management Capabilities:Processor Power Management Capabilities

Effective processor power management enables the computer to automatically balance performance and energy consumption.

Group 0

Index 1

Idle State Count 3

Idle State Type ACPI Idle © States

Nominal Frequency (MHz) 3501

Maximum Performance Percentage 100

Lowest Performance Percentage 45

Lowest Throttle Percentage 45

Performance Controls Type ACPI Performance (P) / Throttle (T) States

Platform Power Management Capabilities:Processor Power Management Capabilities

Effective processor power management enables the computer to automatically balance performance and energy consumption.

Group 0

Index 2

Idle State Count 3
Idle State Type ACPI Idle © States
Nominal Frequency (MHz) 3501
Maximum Performance Percentage 100
Lowest Performance Percentage 45
Lowest Throttle Percentage 45
Performance Controls Type ACPI Performance (P) / Throttle (T) States
Platform Power Management Capabilities:Processor Power Management Capabilities
Effective processor power management enables the computer to automatically balance performance and energy consumption.

Group 0
Index 3
Idle State Count 3
Idle State Type ACPI Idle © States
Nominal Frequency (MHz) 3501
Maximum Performance Percentage 100
Lowest Performance Percentage 45
Lowest Throttle Percentage 45
Performance Controls Type ACPI Performance (P) / Throttle (T) States
Platform Power Management Capabilities:Processor Power Management Capabilities
Effective processor power management enables the computer to automatically balance performance and energy consumption.

Group 0
Index 4
Idle State Count 3
Idle State Type ACPI Idle © States
Nominal Frequency (MHz) 3501
Maximum Performance Percentage 100
Lowest Performance Percentage 45
Lowest Throttle Percentage 45
Performance Controls Type ACPI Performance (P) / Throttle (T) States
Platform Power Management Capabilities:Processor Power Management Capabilities
Effective processor power management enables the computer to automatically balance performance and energy consumption.

Group 0
Index 5
Idle State Count 3
Idle State Type ACPI Idle © States
Nominal Frequency (MHz) 3501
Maximum Performance Percentage 100
Lowest Performance Percentage 45
Lowest Throttle Percentage 45
Performance Controls Type ACPI Performance (P) / Throttle (T) States
Platform Power Management Capabilities:Processor Power Management Capabilities
Effective processor power management enables the computer to automatically balance performance and energy consumption.

Group 0
Index 6
Idle State Count 3
Idle State Type ACPI Idle © States
Nominal Frequency (MHz) 3501
Maximum Performance Percentage 100
Lowest Performance Percentage 45

Lowest Throttle Percentage 45
Performance Controls Type ACPI Performance (P) / Throttle (T) States
Platform Power Management Capabilities:Processor Power Management Capabilities
Effective processor power management enables the computer to automatically balance performance and energy consumption.
Group 0
Index 7
Idle State Count 3
Idle State Type ACPI Idle © States
Nominal Frequency (MHz) 3501
Maximum Performance Percentage 100
Lowest Performance Percentage 45
Lowest Throttle Percentage 45
Performance Controls Type ACPI Performance (P) / Throttle (T) States
Device Drivers:Analysis Success
Analysis was successful. No energy efficiency problems were found. No information was returned.

Tranquility - June 23, 2014, 9:58 am

The Energy Report seems fine and your sleep states are normal according to it.
Were you able to disable hibernation, reboot and tried using sleep mode afterwards?

vtecm - June 23, 2014, 6:51 pm

I disabled hibernation and rebooted.

Will just have to wait and see as it only happens after leaving the computer on sleep for a while.
If I put it in sleep and wake it pretty quickly it usually works fine.

vtecm - July 7, 2014, 6:56 pm

Problem still exists unfortunately. Not sure why this is happening, upgraded probably everything except for ram, could it be that?

Aura - July 8, 2014, 8:11 am

(Jul 7, 2014 06:56 PM)vtecm Wrote: [\[CITE\]](#) Problem still exists unfortunately. Not sure why this is happening, upgraded probably everything except for ram, could it be that?

I doubt the RAM would cause such an issue.

Did you reinstall Windows yet ? Because if you changed everything, I guess you changed the HDD too and reinstalled Windows ?

vtecm - July 8, 2014, 8:16 am

Shouldn't take 5 minutes to warm up. It only happens on sleep mode, when the computer is fully off and turned on it boots very quick.

Yes I reinstalled Windows. Think this is the 3rd operating system I've ran while having this problem, have formatted a few times each os i've had.

Aura - July 8, 2014, 8:17 am

(Jul 8, 2014 08:16 AM)vtecm Wrote: [\[CITE\]](#) Shouldn't take 5 minutes to warm up. It only happens on sleep mode, when the computer is fully off and turned on it boots very quick.

Yes I reinstalled Windows. Think this is the 3rd operating system I've ran while having this problem, have formatted a few times each os i've had.

That's really weird indeed.

The motherboard, CPU, HDD was changed ? Only hardware left is the RAM ?

vtecm - July 9, 2014, 4:28 am

Yes I'm pretty sure just the ram left for the components.

BITW - July 10, 2014, 1:19 am

I think this is a normal matter which happening for me too.

r1seN- - July 10, 2014, 10:18 am

If it isn't software, its most likely your harddrive..?

Aura - July 10, 2014, 10:19 am

(Jul 10, 2014 10:18 AM)Delightful Wrote: [\[CITE\]](#) If it isn't software, its most likely your harddrive..?
If you read every posts before posting, you'll see that the HDD had already been changed.

HackerNoobien - July 11, 2014, 12:23 am

(May 7, 2014 03:26 AM)vtecm Wrote: [\[CITE\]](#) I've been having problems with my computer for under a year now, where when I try to wake my computer from sleep mode it won't load up instantly, it'll wake after a few minutes.

I got a new hard drive and put my OS on that and still hasn't solved the problem.

Specs:

Windows 8 genuine

i7 3770k

ASRock Extreme 4 Z77

8gb Kingston 2x4GB 1333MHZ

Please. Disable sleep mode, sleep mode destroys your hard drive. disable it and you will have no problems

Aura - July 11, 2014, 3:17 am

(Jul 11, 2014 12:23 AM)HackerNoobien Wrote: [\[CITE\]](#) Please. Disable sleep mode, sleep mode destroys your hard drive. disable it and you will have no problems
It's been done already ... read all the posts before posting in a thread.